

**DELHI JAL BOARD: GOVT. OF NCT OF DELHI  
OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)  
ROOM NO. 209, VARUNALAYA PHASE-I  
KAROL BAGH, NEW DELHI – 110005  
# 23558264**

No./DJB/EE(RWH/GWC)/2018/4165.  
To,


DATED: 7/8/18

Manager,  
Suman Vidhya Mandir Sec. School,  
A-57, Bhagirathi Vihar, Delhi-94

**Subject: Adequacy certificate in regard to rain water harvesting system at  
Suman Vidhya Mandir Sec. School, A-57, Bhagirathi Vihar, Delhi-94.**

Please refer to your letter dated 26.07.2018 in which you have informed that Rain Water Harvesting has been installed at your said premises, the rain water harvesting structure was inspected by NGT Joint Inspection Team on dated 28.07.2018 and found sufficient and adequate to harvest the catchment area of your premises.

You are therefore advised to keep are RWH system neat & clean and maintain the same periodically.

  
EE (RWH/GWC)  
EE (G W CELL)  
DELHI JAL BOARD  
VARUNALAYA BHAWAN,  
JHANDEWALLAN, N.D.-05